

File Creation Date: Apr 22nd, 2014
File Type: Firmware Release Note
File Name: RN_HDL-MSPU05.48_V04.01U(2014-04-11).pdf
Product Name: HDL-MSPU05.48
Firmware version: HDL_V04.01U_2014/04/11
Hardware version: HDL-00854A

A. New functions

1- Add Initial mode

Go to “User management” in the HDL-BUS Pro software, enter MAC page, there is an “Initial” option, click it will remove HDL-MSPU05.48 sensor’s all configuration(except the Lux Sensor Adjust function, its adjust value will be saved), and the Subnet ID is still same as before, Device ID will change to the MAC last byte’s value.

Device:	1-78-HDL-MSPU05.48-main sensor	Machine Code:	
Read MAC:	08.76.54.32.34.56.98.78		0876543234569878
Auto MAC:		0015171400971
Manual:		0015171400971
Initial:	Request to initial mode.....		

B. Fixed bugs

None

C. Known issues

None

File Creation Date:	Jan 2 nd , 2014
File Type:	Firmware Release Note
File Name:	RN_HDL-MSPU05.48_V04.01U(2013-12-26).pdf
Product Name:	HDL-MSPU05.48
Firmware version:	HDL_V04.01U_2013/12/26
Hardware version:	HDL-00854A

A. New functions

1- Add "Temperature Sensor" option

Can adjust the temperature of it in the HDL-BUS Pro software. (Note: the HDL-BUS

Pro software version should be V10.18.03.07 or above.)

B. Fixed bugs

None

C. Known issues

None